

Pole Room Mitcham Pole and Lyra Studio Inspection

July 13th 2021

Murray Hare from Catch up productions Pty Ltd ,

completed a 1st inspection at the above pole dance studio .

We found all poles to be in a satisfactory working order, with no obvious signs of wear or movement in any poles or fittings.

However the following suggestions were made for improvement and safety.

*bolt top fixings of poles should be grade 8.8 bolts (currently 4.6 grade)

*check and log all soft slings for wear and in use date, replace regularly as required. (lyra room to be replaced asap, all out of date 4 years plus old)

*check and log all carabiners and shackles for wear and in use date, replace regularly as required.

*start and complete a two weekly log of checks for all poles, lyras and all associated rigging.

I will re check and inspect all of the above next 12 monthly visit

Thanks Murray Hare

Riggers licence 000135930602


Murray Hare
13/7/21 ✓

Studio 2

Lyra


pole room Muteham
July 21

for Lyra location/identification



for pole identification/location.

Studio 3
pole



NOT TO SCALE

7	Check: Good	pass	Check:	Out of useable date X Replace	Check: Good	pass
8	Check: Good	pass	Check:	Out of useable date X Replace	Check: Good	pass
9	Check: Good	pass	Check:	Out of useable date X Replace	Check: Good	pass
10	Check: Good	pass	Check:	Out of useable date X Replace	Check: Good	pass
11	Check: Good	pass	Check:	Out of useable date X Replace	Check: Good	pass
12	Check: NA		Check: NA		Check: NA	
13	Check: NA		Check: NA		Check: NA	
14						
15					NA	

* please see Studio 2 plan for Lyra location/position.

* joining slings to be replaced to enable pass on inspection

POLE ROOM Mitcham Victoria

This inspection: 13/7/21

Next inspection due: 13/7/22

Lyra INSPECTION (Mitcham studio 2)



Pole Number	Roof Attachment	Pass Fail	Joining Sling roof to lyra	Pass <u>Fail</u>	Lyra connections	Pass Fail
1	Check: Good	Pass	Check:	Out of useable date <input checked="" type="checkbox"/> Replace	Check: Good	Pass
2	Check: Good	Pass	Check:	Out of useable date <input checked="" type="checkbox"/> Replace	Check: Good	Pass
3	Check: Good	Pass	Check:	Out of useable date <input checked="" type="checkbox"/> Replace	Check: Good	Pass
4	Check: Good	Pass	Check:	Out of useable date <input checked="" type="checkbox"/> Replace	Check: Good	Pass
5	Check: Good	Pass	Check:	Out of useable date <input checked="" type="checkbox"/> Replace	Check: Good	Pass
6	Check: Good	Pass	Check:	Out of useable date <input checked="" type="checkbox"/> Replace	Check: Good	Pass

POLE ROOM Mitcham Victoria

This inspection: 13/7/21

Next inspection due: 13/7/22

POLE INSPECTION (Mitcham studio 1)

Pole Number	Roof Attachment	Pass <i>Fail</i>	Pole	Pass <i>Fail</i>	Floor / Base	Pass <i>Fail</i>
0	Check:		Check:		Check:	
1	Check: 	Bolts require change to grade 8.8 high tensile	Check: Good	Pole in good working order <i>pass</i>	Check: Good 	<i>pass</i>
2	Check:		Check:		Check:	
3	Check:		Check:		Check:	
4	Check:		Check:		Check:	
5	Check:		Check:		Check:	
6	Check:		Check:		Check:	
7	Check:		Check:		Check:	
8	Check:		Check:		Check:	
9	Check:		Check:		Check:	
10	Check:		Check:		Check:	
11	Check:		Check:		Check:	
12	Check:		Check:		Check:	

- * Note positions for other poles in this studio, but currently no poles installed in these positions.
- * 8.8 grade bolts should be installed into roof attachment.